

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/10/2025

Document Number:

708907128

**FIELD INSPECTION FORM**

Loc ID 323862 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211028	WELL	PR	08/30/2016	GW	045-06786	OXY USA INC MV 45-10	PR

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Sign weathered & cracking but still legible at this time		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign weathered & cracking but still legible at this time		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Other	# 3		
Comment:	PRV & rupture disc vent lines on separator do not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC Rule 608		Date: 08/17/2025
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 211028 Type: WELL API Number: 045-06786 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in most areas
		Culverts				
		Gravel				Sparse to none in most sections
		Ditches				
Sediment Traps						
		Compaction				Small amount of light compaction
Check Dams						
Compaction						Light compaction in some areas
		Check Dams				
Ditches						
		Rip Rap				
Rip Rap						

Comment:

Corrective Action:

Date:

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 08/05/2025 at approximately 10:24 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad                      Location # 323862 in Garfield County Colorado.                      Location is within High Priority/Density/Black Bear Habitat areas.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Equipment - PRV &amp; rupture disc vent lines on separator do not comply with CECMC pressure safety device rules - Comply with rule 608 with a CA date of 08/17/2025</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p>	smelserw	08/10/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907129	Inspection/Audit 708907128 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7181498">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7181498</a>
708907130	Inspection/Audit 708907128 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7181499">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7181499</a>

