

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC REDA TANK FARM

Location ID: 335111

Facility ID: 434770




Photo # 9291 From entrance to location

Photo # 9292 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC REDA TANK FARM

Location ID: 335111

Facility ID: 434770



Photo # 9293 Location



Photo # 9294 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC REDA TANK FARM

Location ID: 335111

Facility ID: 434770



Aug 7, 2025 at 12:48:14 PM
+39.480025,-108.099501



Aug 7, 2025 at 12:52:31 PM
+39.480092,-108.099791

Photo # 9295 Location

Photo # 9296 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC REDA TANK FARM

Location ID: 335111

Facility ID: 434770



Photo # 9297 Open ended load line



Photo # 9298 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC REDA TANK FARM

Location ID: 335111

Facility ID: 434770



Photo # 9299 Open ended load line



Photo # 9300 PRV vent line on tank burner does not comply with CECMC pressure safety device rules & general safety rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC REDA TANK FARM

Location ID: 335111

Facility ID: 434770



Photo # 9301 Tank lacks required labeling

Photo # 9302 Tank lacks required labeling

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC REDA TANK FARM

Location ID: 335111

Facility ID: 434770



Photo # 9303 Tank lacks required labeling

Photo # 9304 Tank lacks required labeling