

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/04/2025

Submitted Date:

08/04/2025

Document Number:

715801278

**FIELD INSPECTION FORM**

Loc ID 336406 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

12 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240786	WELL	TA	08/13/2019	OW	123-08574	JILLSON 3	TA

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate, the sign is fading and will need to be replaced in the near future.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Tall vegetation needs to be removed		
Corrective Action:	Comply with Rule 606		Date: 08/11/2025
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Fabricated steel pipe		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1	corrective date	
Comment:	Over run with tall vegetation.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	electric panel is shut off, meter box has no meter & transformers,all unused.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor no power connected		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	unattached to the well, horse head is lying on the ground.		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240786 Type: WELL API Number: 123-08574 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, the well is part of a 901 Order.  
TA Form 04(OBJ-TA)-00 Doc 403006261 11-4-2013.  
Form 05B-00-Inactive Well Notice Doc # 403235593 date submitted 11-22-2022. The  
inactive date was 7-31-2011. The last MIT Was 9-4-2019 Form 21 Doc # 402165748 & is  
due for an updated test, Perform successful mechanical integrity test. If a successful MIT  
can not be performed within 30 day CA time the well must be plugged within 3 months  
per Rule 417 and 210. CA date 10-4-2024.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/02/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface, submit test results to the ECMC.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 12-4-2025 at approximately 1415 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: KP Kauffman                      Location ID # 336406                      Well Name: Jillson 3                      API # 05-123-08574                      County: Weld                      Temperature: 88*                      Weather: Clear.                      Location: dry.                      While there, I observed a wellsite, SI at the time of the inspection.                      During this inspection, I observed the following possible compliance issue:                      606 housekeeping: CA date 8-11-2025.                      Any corrective actions from previous Inspections that have not been addressed are still applicable.                      See attached photos                      A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	08/04/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404304959	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174135">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174135</a>
715801279	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174123">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174123</a>