

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/11/2025

Submitted Date:

08/11/2025

Document Number:

698707931

**FIELD INSPECTION FORM**

Loc ID 333716 Inspector Name: Serna, Abe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
 Address: 1875 LAWRENCE ST STE 1150  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,	719-846-7898	cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276208	WELL	PR	04/15/2005	CBM	071-08303	SANTA FE 43-27 TR	PR

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Well sign adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:   
 Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds		
Corrective Action:	Comply with rule 605	Date:	08/18/2025

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

						corrective date
Type: Progressive Cavity	# 1					
Comment:						
Corrective Action:						Date:
Type: Prime Mover	# 1					
Comment:						
Corrective Action:						Date:
Type: Bradenhead	# 1					
Comment:						
Corrective Action:						Date:
Type: Deadman # & Marked	# 4					
Comment:						
Corrective Action:						Date:
Type: Vertical Separator	# 1					
Comment:						
Corrective Action:						Date:
Type: Ancillary equipment	# 2					
Comment:						
Corrective Action:						Date:
Type: Gas Meter Run	# 1					

Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	270539	1126314	
	281072	1393345	
	281072	1393345	

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On 8/11/25 at approximately 9:45 AM I, Inspector Abe Serna, conducted an on-site inspection.                      Location: Santa Fe 43-27 TR                      Operator: ENR                      API#: 071-08303                      County: LAS ANIMAS                      While there, I observed a PR Well                      During this inspection the following possible compliance issues were observed:                      Weeds around wellhead and equipment. needs to be cut and removed                      See attached photo #.2                      Corrective Action Date: 8-18-25                      Weather conditions: Sunny                      A follow up on this site inspection needs to be completed .                      Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p> <p>Any corrective actions from previous inspections that have not been addressed are still applicable</p>	sernaa	08/11/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698707932	Photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7182163">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7182163</a>