

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2025

Submitted Date:

08/06/2025

Document Number:

716301375

FIELD INSPECTION FORM

Loc ID 307438 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113399	PIT	AC	06/06/2023		-	DAVE 21-31 ONSITE	AC
217664	WELL	PR	09/17/2005	CBM	071-06443	DAVE 21-31	PR

General Comment:

[CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	PHOTO 4, 5 & 6: TRASH OR DEBREE.		
Corrective Action:	REMOVE TRASH AND DEBREE PER RULE 606.	Date:	08/22/2025
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 8: UNUSED EQUIPMENT (1" RISER NOT MARKED OR IN USE).		
Corrective Action:	REMOVE OR MARK RISER AS TO WHAT IS CARRIES ie. Gas water etc per rule606. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION IMMEDIATE ACTION IS REQUIRED.	Date:	
Type	WEEDS		
Comment:	PHOTO 7: WEEDS ARE STARTING TO ENCROACH NEAR WELLHEAD.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	08/22/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Progressive Cavity	# 1		
Comment:	ELECTRIC DRIVE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 113399 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 217664 Type: WELL API Number: 071-06443 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/20/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 ON FILE

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 113399 Lat: 37.308066 Long: -104.718130

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	113399	403418220	

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary This is a follow up to insp. doc #716301007, meter has been callibrated however the 1" riser was not addressed and there are new ca's. On Tuesday 8-6-2025 at approximately 13:38, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location Dave 21-31 API# 05-071-06443 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 4, 5 & 6: TRASH OR DEBREE. REMOVE TRASH AND DEBREE PER RULE 606. CA DATE 8-22-2025. PHOTO 7: WEEDS ARE STARTING TO ENCROACH NEAR WELLHEAD. MAINTAIN WEEDS PER RULE 606. CA DATE 8-22-2025. PHOTO 8: UNUSED EQUIPMENT (1" RISER NOT MARKED OR IN USE). REMOVE OR MARK RISER AS TO WHAT IS CARRIES ie. Gas water etc per rule 606. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION IMMEDIATE ACTION IS REQUIRED. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	08/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301378	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7182186