

WELL NAME: MUFFINS 14-18, API #: 071-8759, INSP. # 716301357



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: WEEDS ARE ENCROACHING ON WELLHEAD EQUIPMENT. MAINTAIN WEEDS PER RULE 606. CA DATE 8-16-2025.



PHOTO 5: CULVERT IS PLUGGED. Install or repair required BMPs per Rule 1002.f.(2)C . CA DATE 6/13/2025.



WGS84
±15ft

37.25175, -104.72062

ft
±10ft

7239

°M
±11

SW229



Colorado Oil & Gas Conservation commission
© 05-Aug-25 14:38:29

PHOTO 6: DOWN SLOP SIDE OF CULVERT IS COMPLETELY COVERED. Install or repair required BMPs per Rule 1002.f.(2)C. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.



PHOTO 7: PRODUCE WATER PIT LINER IS COMPROMISED. REPAIR LINER OR (Rule 910) Reduce fluid level in pit, contact ECOM EPS staff for directives. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION IMMEDIATE ACTION IS REQUIRED.

WGS84
±13ft

37.25134, -104.72054

ft
±10ft

7237

°M
±21

E93



Colorado Oil & Gas Conservation commission
© 05-Aug-25 14:40:42

PHOTO 8: PRODUCE WATER PIT LINER IS COMPROMISED. REPAIR LINER OR (Rule 910) Reduce fluid level in pit, contact ECOM EPS staff for directives. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION IMMEDIATE ACTION IS REQUIRED.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources