

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/11/2025

Submitted Date:

08/11/2025

Document Number:

698707939

FIELD INSPECTION FORM

Loc ID 333660 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273821	WELL	PR	05/01/2005	CBM	071-08218	HG DURAN 34-27 TR	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type OTHER		
	Comment: Well sign adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Good Housekeeping:

Type	OTHER		
	Comment: Less than 2-feet of freeboard		
Corrective Action:	Lower fluid level so at least two feet of freeboard exists per Rule 909.c.	Date:	08/25/2025

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Progressive Cavity	# 1				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				

Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 273821 Type: WELL API Number: 071-08218 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment: Pit needs to be pulled

Corrective Action

Date:

Fencing:

Fencing Type: None Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	278880	1139737	
	281445	1393677	
	281445	1393677	

ECMC Comments

Comment	User	Date
<u>Routine Inspection</u>	sernaa	08/11/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698707940	Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7182407