

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2025

Submitted Date:

08/11/2025

Document Number:

716300988

FIELD INSPECTION FORM

Loc ID 324565 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10816
Name of Operator: SILVER MOUNTAIN ENERGY LLC
Address: 31487 STATE HIGHWAY 37
City: HINTON State: OK Zip: 73047

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Flick, Jay	(580) 799-1075	jay@sme.llc	All Forms
Wright, Lonnie	(405) 542-7836	lonnie@sme.llc	All Forms
,		dnr_ecmc_engineering@state.co.us	
Wright, Taylir	(405) 952-4604	taylir@sme.llc	All Forms

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265121	WELL	PR	09/01/2024	CO2	055-06285	CADDELL 1	PR
435037	WELL	PR	09/01/2024	CO2	055-06312	Caddell 2	PR
439694	WELL	SI	12/01/2024	LO	055-06319	Caddell 3	SI

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	PHOTO 1: CURRENT OPERATOR IS NOT LISTED ON WELL SIGN/ API # IS NOT ACCURATE ECMC RECORDS SHOW CADDELL #1 API # IS 05-055-06285 AND 911 IS NOT INCLUDED AS AN EMERGENCY CONTACT ON WELL SIGN. PHOTO 2: CURRENT OPERATOR IS NOT LISTED ON WELL SIGN/911 IS NOT INCLUDED AS AN EMERGENCY CONTACT ON WELLSIGN. PHOTO 3: CURRENT OPERATOR IS NOT LISTED ON WELL SIGN/ API # IS NOT ACCURATE. ECMC RECORDS SHOW CADDELL #3 API # IS 05-055-06319 AND 911 IS NOT INCLUDED AS AN EMERGENCY CONTACT ON WELL SIGN.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	08/22/2025

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 8: TALL SHRUBS AROUND LOCATION.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	08/22/2025

Overall Good:

Spills:

Type	Area	Volume		
In Containment:	No			
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:


			corrective date
Type: Gathering Line	# 2		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>
Type: Deadman # & Marked	# 9		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Venting:

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>



Inspected Facilities

Facility ID: 265121 Type: WELL API Number: 055-06285 Status: PR Insp. Status: PR

Producing Well

Comment:	CADDELL #1 WAS SHUT IN IN FEBUARY 2019 AND THEN PUT ON PRODUCTION IN MAY 2023 WITH NO MIT ON FILE.	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 10/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 305 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action: **Date:** _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435037 Type: WELL API Number: 055-06312 Status: PR Insp. Status: PR

Producing Well

Comment:	CADDELL #2 WAS SHUT IN IN APRIL 2019 AND THEN PUT ON PRODUCTION IN MAY 2023 WITH NO MIT ON FILE. CAPTUREPOINT LLC. FILED A FORM 4 Alternative to MIT Request (DOC. #402919609) THAT WAS APPROVED ON 2/1/2022. THE APPROVAL WAS contingent on the well being returned to production BY 1-30-2023, THE WELL WAS NOT RETURED TO PRODUCTION UNTIL 5-1-2023.	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 10/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: **Date:** _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439694 Type: WELL API Number: 055-06319 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:	CADDELL #3 WAS SHUT IN IN APRIL 2019 AND THEN PUT ON PRODUCTION IN MAY 2023 WITH NO MIT ON FILE. CAPTUREPOINT LLC. FILED A FORM 4 Alternative to MIT Request (DOC. #402919620) THAT WAS APPROVED ON 2/1/2022. THE APPROVAL WAS contingent on the well being returned to production BY 1-30-2023, THE WELL WAS NOT RETURED TO PRODUCTION UNTIL 5-1-2023.	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 10/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #713601422, CA HAS BEEN ADDRESSED. HOWEVER THERE ARE NEW CORRECTIVE ACTIONS LISTED IN THIS DOCUMENT.	beardslt	05/19/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301383	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7182477