

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2025

Submitted Date:

08/11/2025

Document Number:

694500785

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Penner, Annalee		Annalee.Penner@fulcrumeo.com	
Fischer, Alex		alex.fischer@state.co.us	
Blohm, Justin	520-820-2380	justin.blohm@fulcrumeo.com	
Rikki Ross	417-773-2341	rikki.ross@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
491019	SPILL OR RELEASE	AC	07/29/2025		-	SU 0680 #2-4H	EI

General Comment:

On 8/1/25 ECMC staff, Kris Neidel inspected spill number 491019. Weather was 75 degrees and mostly sunny. The following was observed: Secondary containment area was stained with oil and salts, appeared from recent spill. Pump houses inside the containment area were oily on and around the pump skid. Minimal standing fluid inside tank battery. There was no obvious sign that fluid had infiltrated to the adjacent pad. Corrective Actions: remove areas of observable hydrocarbon and salts from inside the secondary containment area. Water wash shall be disposed of as appropriate waste, at minimum E&P waste. See attached photos.

Inspected Facilities

Facility ID: 491019 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Secondary containment area was stained with oil and salts, appeared from recent spill. Pump houses inside the containment area were oily on and around the pump skid.

Corrective Action: remove areas of observable hydrocarbon and salts from inside the secondary containment area. Water wash shall be disposed of as appropriate waste, at minimum E&P waste.

Date: 09/01/2025

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500786	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7183137