

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2025

Submitted Date:

08/11/2025

Document Number:

719500302

**FIELD INSPECTION FORM**

Loc ID 335170 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                    | Comment |
|--------------|-------|--|---------|
| , TEP        |       | ECMCInspectionReports@flywheelenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 210792      | WELL | PR     | 12/02/1987  | GW         | 045-06550 | CHEVRON MV-22-20  | PR          |
| 283746      | WELL | PR     | 09/05/2006  | GW         | 045-11992 | CHEVRON GM 443-20 | PR          |
| 283750      | WELL | PR     | 03/10/2006  | GW         | 045-11989 | CHEVRON GM 533-20 | PR          |
| 283751      | WELL | PR     | 03/10/2006  | GW         | 045-11990 | CHEVRON GM 543-20 | PR          |
| 283752      | WELL | PR     | 03/10/2006  | GW         | 045-11991 | CHEVRON GM 433-20 | PR          |

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 8/8/2025 at approximately 11:15, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE at Location ID #335170 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

| <b>Signs/Marker:</b> |  |       |  |
|----------------------|--|-------|--|
| Type                 | WELLHEAD   |       |  |
| Comment:             |  |       |  |
| Corrective Action:   |  | Date: |  |
| Type                 | TANK LABELS/PLACARDS   |       |  |
| Comment:             |  |       |  |
| Corrective Action:   |  | Date: |  |
| Type                 | OTHER  |       |  |
| Comment:             | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. |       |  |
| Corrective Action:   |  | Date: |  |
| Type                 | BATTERY  |       |  |
| Comment:             |  |       |  |
| Corrective Action:   |  | Date: |  |

|                                  |                   |       |       |
|----------------------------------|-------------------|-------|-------|
| <b>Emergency Contact Number:</b> |                   |       |       |
| Comment:                         | 911/(970)285-9377 |       |       |
| Corrective Action:               |                   | Date: | _____ |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |
|                |      |        |  |

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

| <b>Fencing/:</b>   |                  |       |  |
|--------------------|------------------|-------|--|
| Type               | SEPARATOR        |       |  |
| Comment:           | Livestock panels |       |  |
| Corrective Action: |                  | Date: |  |
| Type               | TANK BATTERY     |       |  |
| Comment:           | Livestock panels |       |  |
| Corrective Action: |                  | Date: |  |
| Type               | WELLHEAD         |       |  |
| Comment:           | Livestock panels |       |  |
| Corrective Action: |                  | Date: |  |

| <b>Equipment:</b>  |     |       | corrective date |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 5 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

|                                   |     |  |       |
|-----------------------------------|-----|--|-------|
| Type: Gas Meter Run               | # 9 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Bradenhead                  | # 5 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Bird Protectors             | # 5 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Horizontal Heated Separator | # 9 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 200 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Metal    |          |                     |                     |             |
| Comment: |          |                     |                     |             |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 210792 Type: WELL API Number: 045-06550 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283746 Type: WELL API Number: 045-11992 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283750 Type: WELL API Number: 045-11989 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283751 Type: WELL API Number: 045-11990 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283752 Type: WELL API Number: 045-11991 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Check Dams              |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 719500303    | Photo Log   | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7183290">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7183290</a> |