

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2025

Submitted Date:

08/05/2025

Document Number:

709100531

FIELD INSPECTION FORM

Loc ID: 442964 Inspector Name: Heibel, Krystal On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 35080
Name of Operator: GRAND MESA OPERATING CO
Address: 1700 N WATERFRONT PKWY B600
City: WICHITA State: KS Zip: 67206

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent
,	1-316-633-6013	jcrombie@gmocks.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446515	LOCATION	AC	06/09/2025		-	THE SEARCHERS 1-25	EI

General Comment:

On August 1, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the Buzzs Boat 14 location (Facility ID: 442964).
This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Unused equipment located on site / Comly with Rule 606

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

Comment: Drips and drabs observed on pad material

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 09/01/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 446515 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404306258	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175536
709100532	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175517