

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2025

Submitted Date:

08/05/2025

Document Number:

709100533

**FIELD INSPECTION FORM**

Loc ID 456700 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 35080

Name of Operator: GRAND MESA OPERATING CO

Address: 1700 N WATERFRONT PKWY B600

City: WICHITA State: KS Zip: 67206

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
,	1-316-633-6013	jcrombie@gmocks.com	All Inspections
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent
Kyle Waggoner		kyle.waggoner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456700	Location	AC			-	THE SEARCHERS TK BAT LOC 1	EI

**General Comment:**

On August 1, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the THE SEARCHERS TK BAT LOC/1 location (Location ID: 456700).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type WEEDS

Comment: Weeds observed in secondary containment. / Comply with Rule 606

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Burrows present and observed in berms.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 09/01/2025

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 456700 Type: Location API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404306259	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175537">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175537</a>
709100534	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175518">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175518</a>