

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2025

Submitted Date:

08/12/2025

Document Number:

715202761

FIELD INSPECTION FORM

Loc ID 314204 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------------------|---------|
| Reed, Shawn | 303-562-6530 | shawn@sreedconsulting.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228022 | WELL | PR | 04/01/2024 | GW | 099-06349 | DANIELS 1-27 | PR |

General Comment:

This is a field audit of the scout card, related documents and the location by SE Compliance Specialist Brian Welsh

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through pasture | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|-------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence at unit | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Stickers on tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|------------------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Pipe fence around HGS | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Wire fence around tank | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|--------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | HHS between unit and meter run | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | American unit | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Arrow gas engine | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|--|------------------|
| Type: Ancillary equipment | # 1 | |
| Comment: | Gas scrubber (base of unit) | |
| Corrective Action: | Audible leak was detected at time of inspection coming from the hose on the regulator to the base of the unit. Repair or replace the hose to stop the leak of well gas | Date: 08/13/2025 |
| Type: Gas Meter Run | # 1 | |
| Comment: | Meter shed on east side of location | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE | 1 | OTHER | STEEL AST | | 37.847810,-102.461790 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|---------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 210bbbs |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 228022 Type: WELL API Number: 099-06349 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Production reports are up to date at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | Compaction | Pass | | | |

Comment: [Location is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 715202765 | north side of wellhead looking southeast | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7185187 |
| 715202766 | east side of meter shed looking west | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7185188 |