

Inspection Photos
Location Name: Max Serafini 'B'-62N68W 28NESW
Location ID: 318224



No access

No access

Inspection Photos
Location Name: Max Serafini 'B'-62N68W 28NESW
Location ID: 318224



Sign

Overgrown Vegetation

Inspection Photos
Location Name: Max Serafini 'B'-62N68W 28NESW
Location ID: 318224



Horsehead on pumping unit appears to have bird nest but doesn't appear to be active. Consult with CPW.

Unused Equipment

Inspection Photos
Location Name: Max Serafini 'B'-62N68W 28NESW
Location ID: 318224



Overgrown Vegetation

Torn down barbwire fence

Inspection Photos
Location Name: Max Serafini 'B' -62N68W 28NESW
Location ID: 318224



Packing on the well appears to be emitting emissions and needs to be fix or replaced.

Electrical Equipment

Inspection Photos
Location Name: Max Serafini 'B'-62N68W 28NESW
Location ID: 318224



Exposed wires for pumping unit electrical box/ transformers appears to be a safety hazard.

Exposed wires for pumping unit electrical box/ transformers appears to be a safety hazard.

Inspection Photos

Location Name: Max Serafini 'B'-62N68W 28NESW

Location ID: 318224



Header Location/ overgrown vegetation



Unmarked Risers/ Overgrown vegetation

Inspection Photos

Location Name: Max Serafini 'B'-62N68W 28NESW

Location ID: 318224



Unmarked Risers/ Overgrown vegetation

Unmarked Risers/ Overgrown vegetation

Inspection Photos

Location Name: Max Serafini 'B'-62N68W 28NESW

Location ID: 318224



Location- Drone Photo



Header Location- Drone Photo