

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2025

Submitted Date:

08/06/2025

Document Number:

707801750

FIELD INSPECTION FORM

Loc ID 313400 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 3975
Name of Operator: ARGALI EXPLORATION COMPANY
Address: PO BOX 416
City: RANGELY State: CO Zip: 81648

Findings:

- 12 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------------|---------------------------------|
| General, contact | | argaliexplorationcompany@gmail.com | all inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 296464 | WELL | PR | 10/01/2024 | GW | 081-07442 | SIMPSON 25-4 | PR |

General Comment:

[ECMC Inspection Report Summary](#)
On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Argali Exploration Simpson 25-4, at Location # 313400 in Moffett County Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.
All valves on well head, separator and sales line are open and have pressure.
During this inspection the following possible compliance issues were observed:
1. Secondary containment is insufficient.
2. Weeds throughout location and access road.
3. 1000-gallon methanol tank is unused equipment and not properly contained.
4. Lack of battery signage
5. Well signage lacks information

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|--|-------|------------|
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Signage lacks proper information | | |
| Corrective Action: | Provide proper signage | Date: | 09/06/2025 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Lack of battery signage | | |
| Corrective Action: | Provide proper signage | Date: | 09/06/2025 |

| | | | |
|----------------------------------|--------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 970-629-1906 | | |
| Corrective Action: | | | Date: _____ |

| Good Housekeeping: | | | |
|---------------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | 1000-gallon methanol tank is unused equipment and not properly contained. | | |
| Corrective Action: | Remove or put into service and properly contain. | Date: | 09/06/2025 |
| Type | WEEDS | | |
| Comment: | Weeds throughout location and access road. | | |
| Corrective Action: | Remove weeds | Date: | 09/06/2025 |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Equipment: | | | corrective date |
|---------------------|-----------|-------|-----------------|
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Well head | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|------------------|
| Earth | | | | |
| Comment: | Secondary containment is insufficient. | | | |
| Corrective Action: | Install or maintain containment to ensure spill or released materials will be maintained with containment structure. | | | Date: 09/06/2025 |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 296464 Type: WELL API Number: 081-07442 Status: PR Insp. Status: PR

Producing Well

Comment: [All valves are open to sales with pressure on guages.](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404308056 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7177365 |
| 707801752 | Photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7177311 |