

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2025

Submitted Date:

08/06/2025

Document Number:

707801751

FIELD INSPECTION FORM

Loc ID 313289 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 3975
Name of Operator: ARGALI EXPLORATION COMPANY
Address: PO BOX 416
City: RANGELY State: CO Zip: 81648

Findings:

- 19 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General, contact		argaliexplorationcompany@gmail.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284610	WELL	PR	02/01/2024	GW	081-07303	SIMPSON 24-10	PR

General Comment:

[ECMC Inspection Report Summary](#)
On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Argali Exploration Simpson 24-10, at Location # 313289 in Moffett County Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.
During this inspection the following possible compliance issues were observed:

1. Stored equipment(separator)
2. Random debris
3. 500-gallon methanol tank is unused equipment and not properly contained.
4. Lack of battery signage
5. Well signage lacks information
6. Open load line
7. Tank label missing information
8. PRV's lacking caps

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:		
Type	WELLHEAD	
Comment:	Well signage lacks information	
Corrective Action:	Provide proper signage	Date: <u>09/06/2025</u>
Type	CONTAINERS	
Comment:		
Corrective Action:		Date:
Type	BATTERY	
Comment:	Lack of battery signage	
Corrective Action:	Provide proper signage	Date: <u>09/06/2025</u>
Type	OTHER	
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.	
Corrective Action:		Date:
Type	TANK LABELS/PLACARDS	
Comment:	Tank label missing information	
Corrective Action:	Provide proper labeling	Date: <u>09/06/2025</u>

Emergency Contact Number:		
Comment:	<u>970-629-1906</u>	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	OTHER	
Comment:	PRV's lacking caps	
Corrective Action:	Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.	Date: <u>09/06/2025</u>
Type	DEBRIS	
Comment:	Random debris	
Corrective Action:	Remove debris	Date: <u>09/06/2025</u>
Type	OTHER	
Comment:	Open hole for wild life	
Corrective Action:	Eliminate wildlife hazard.	Date: <u>09/06/2025</u>
Type	OTHER	
Comment:	500-gallon methanol tank is unused equipment and not properly contained.	
Corrective Action:	Remove or put into service and properly contain	Date: <u>09/06/2025</u>
Type	OTHER	
Comment:	Open load lines	
Corrective Action:	Cap or plug load lines	Date: <u>09/06/2025</u>
Type	STORAGE OF SUPL	
Comment:	Stored equipment(separator)	

Corrective Action: Remove or put into service.	Date: 09/06/2025
---	-------------------------

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No
 Comment:
 Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1	Comment: Well head	
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2	Comment: 1 is unused	
Corrective Action:			Date:
Type: Gas Meter Run	# 1	Comment:	
Corrective Action:			Date:
Type: Ancillary equipment	# 1	Comment: 500-gallon methanol tank is unused equipment and not properly contained.	
Corrective Action:			Date:
Type: Bird Protectors	# 1	Comment:	
Corrective Action:			Date:
Type: Bradenhead	# 1	Comment:	
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		STEEL AST		
Comment:	Tank lacks quantity				
Corrective Action:					Date:

Paint

Condition	<input style="width:500px" type="text"/>
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment:		
Corrective Action:		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 284610 Type: WELL API Number: 081-07303 Status: PR Insp. Status: PR

Producing Well

Comment: [Valves ar all open to sales.](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404308059	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7177366
707801753	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7177312