

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/05/2025

Document Number:

713302183

FIELD INSPECTION FORM

Loc ID 321493 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CivitasResources		Inspections@civiresources.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206679	WELL	PR	05/01/2025	GW	014-06174	VARRA 1-21	PR

General Comment:

[well site and facility inspection](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	well head area, overgrown vegetation, photos 3 & 4		
Corrective Action:	Comply with Rule 606	Date:	08/12/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	chain linc panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	post and wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	post and wire		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	LOTO		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	automation panels		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	269 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	53 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: shared with crude tank					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 206679 Type: WELL API Number: 014-06174 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 10/10/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted an on-site inspection. Location: Varra 1-21 Operator: Extraction API#: 114-06174 County: Broomfield While there, I observed well site with production equipment. During this inspection the following possible compliance issues were observed: Overgrown vegetation, Rule 606 corrective action date 8-12-2025 photos 3 & 4 Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	08/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404306572	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7176209
713302184	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7176202