

Dwinell
© 03-Jun-25 01:52:09 PM
ECMC Environmental Inspection

An earthen pit was visible on location. No liner was visible. No fluid was visible in the pit. An uncapped metal flowline was visible on the western side of the pit.

The Dwinell Tank Battery (Facility ID 465486) is visible in the background and will be addressed in a separate inspection.

WGS84 $\pm 18\text{ft}$ 40.82176, -106.23275 $\pm 5\text{m}$ 2462 ± 11 NE23



ECMC
Environmental
Field Inspection



Dwinell
© 03-Jun-25 01:52:52 PM
ECMC Environmental Inspection

Weeds were visible within the pit. Metal netting/fencing was visible covering portions of the pit.

WGS84
±15ft


40.82192, -106.23269

m
±4m

2456

°T
±11

SE119



ECMC
Environmental
Field Inspection



Dwinell
© 03-Jun-25 01:54:58 PM
ECMC Environmental Inspection

Signage with emergency contact number was visible in front of the well house.

WGS84 $\pm 24\text{ft}$ 40.82191, -106.23263 $\Delta^m_{\pm 4m}$ 2462 $\triangle^{\circ, T}_{\pm 11}$ NE67



ECMC
Environmental
Field Inspection



Dwinell
© 03-Jun-25 01:55:28 PM
ECMC Environmental Inspection

An oily rag was visible within the well house.

WGS84
±21ft

40.82189, -106.23259

m
±4m

2463

°T
±11

W273



ECMC
Environmental
Field Inspection



Dwinell
© 03-Jun-25 01:55:59 PM
ECMC Environmental Inspection

Trash (rebar, cans, bottles) was visible adjacent to the former pumping unit foundation.

WGS84 $\pm 22\text{ft}$ 40.82206, -106.23258 Δ $\pm 3\text{m}$ 2463 \triangle ± 11 SE134



ECMC
Environmental
Field Inspection



Dwinell
© 03-Jun-25 01:57:21 PM
ECMC Environmental Inspection