



ECMC
Environmental
Field Inspection



Federal #9-27
© 04-Jun-25 02:56:37 PM
ECMC Environmental Inspection

Looking at well pad from access road. The well appears to have been plugged and abandoned.

WGS84
±10ft


40.71925, -106.13508

m
±3m

2541

°T
±11

NW317



ECMC
Environmental
Field Inspection



Federal #9-27
© 04-Jun-25 02:57:16 PM
ECMC Environmental Inspection

Vegetation in the vicinity of the former well appears limited in comparison to the surrounding field.

WGS84 40.71934, -106.13521 Δ m \pm 3m 2540 Δ m \pm 11 SW240



ECMC
Environmental
Field Inspection



Federal #9-27
© 04-Jun-25 02:57:31 PM
ECMC Environmental Inspection

Trash (metal and wire) is visible on location.