

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2025

Submitted Date:

08/13/2025

Document Number:

716900104

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
320062 \_\_\_\_\_ Huck, Keith \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email         | Comment                         |
|--------------|-------|---------------|---------------------------------|
| ,            |       | cogcc@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 202467      | WELL | PR     | 01/01/2023  | GW         | 001-07872 | UPRR 23 PAN AM M 3 | SI          |

**General Comment:**

[Follow-Up Inspection DOC#717000234/No corrective Actions from the previous inspections has been adressed. No Equipment has changed](#)

**Location**

Overall Good:

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | BATTERY  |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |          |       |       |
|---------------------------|----------|-------|-------|
| Emergency Contact Number: |          |       |       |
| Comment:                  | Adequate |       |       |
| Corrective Action:        |          | Date: | _____ |

|                           |   |       |            |
|---------------------------|---|-------|------------|
| <b>Good Housekeeping:</b> |   |       |            |
| Type                      | WEEDS   |       |            |
| Comment:                  | Weeds throughout location. It appears that no corrective action measures were taken from prior inspection and now the location is overgrown with weeds. See attached photos |       |            |
| Corrective Action:        | Comply with Rule:606  | Date: | 08/20/2025 |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 202467 Type: WELL API Number: 001-07872 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment  | User  | Date       |
|--|-------|------------|
| <p><a href="#">ECMC Inspection Report Summary</a><br/>                     On (8/13/25) at approximately (10:28am). I, Inspector Keith Huck, conducted an on-site inspection.<br/>                     Operator: KPK<br/>                     Location name: UPRR 23 PAN AM M#3<br/>                     API #05-001-07872<br/>                     Location ID #:320062<br/>                     County: Adams<br/>                     While there, I observed a (SI) well.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     Weeds throughout location and wellhead<br/>                     Comply with Rule:606<br/>                     Corrective Action Date:8/20/2025<br/>                     These corrective actions were not addressed from the last inspection DOC#717000234<br/>                     A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.<br/>                     This is a summary of inspection report.</p> | huckk | 08/13/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 716900105    | Inspection Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186871">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186871</a> |