

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Remediation Projects # 37605 and # 37609. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Well Name: Jepsen 4 Well

Remediation Project #: 37605

Well API #: 05-123-13650

Tank Battery Name: Jepsen T3N-R65W-S2 L04 Tank Battery

Remediation Project #: 37609

Facility ID: 487654

Date of Inspection: 08/14/2025

Weather: Partly cloudy, 80°F

Site is located within or adjacent to:

- Freshwater Emergent Wetlands (~40 ft east)
- Surface water (~77 ft east)
- Bald Eagle Roost Site High Priority Habitat (within)
- Mule Deer Severe Winter Range High Priority Habitat (within)

Current site status:

- The excavation at the former well location has been backfilled.
- The tank battery has been decommissioned.
- No remedial activities present.
- Unused ancillary equipment is present adjacent to the former well location.
- Trash (multiple pieces of plastic and metal) and E&P waste (red metal pipe) are present on location.
- A hole/area of ground subsidence is present in the vicinity of the former separator.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash (multiple pieces of plastic and metal) and E&P waste (red metal pipe) are present on location.		
Corrective Action:	Comply with Rule 606 d.	Date:	08/21/2025
Type	UNUSED EQUIPMENT		
Comment:	Unused ancillary equipment is present adjacent to the former well location.		
Corrective Action:	Comply with Rule 606 a.	Date:	08/29/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 245855 Type: WELL API Number: 123-13650 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487654 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation Project # 37605 was created for the plugging and abandonment of the Jepsen 4 Well and decommissioning of the associated flowline. The excavation at the former well location has been backfilled. No remedial activities present. Quarterly reporting is required under Remediation Project # 37605.

Remediation Project # 37609 was created for decommissioning of the Jepsen T3N-R65W-S2 L04 Tank Battery. The tank battery has been decommissioned. No remedial activities present. Quarterly reporting is required under Remediation Project # 37609.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [A hole/area of ground subsidence is present in the vicinity of the former separator.](#)

Corrective Action: [Comply with Rule 1002.f.](#)

Date: 08/29/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100360	ECMC Photo Log - Jepsen 4 Well & Jepsen T3N-R65W-S2 L04 Tank Battery - 08.14.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7188866