

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

08/14/2025

Document Number:

717100326

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Rollins, Grace _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Watzman, Ross		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442351	SPILL OR RELEASE	CL	03/06/2019		-	SPILL/RELEASE POINT	EI

General Comment:

[ECMC Field Inspection Report Summary](#)
This is an environmental inspection to determine progress on Spill ID 442351. A desktop inspection of Remediation Project # 11848 was also included in the scope of this inspection. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill Name: McCallum 33 Flowline
Spill ID: 442351
Spill/Release closed with work proceeding under Remediation Project #: 11848
Reported Date of Discovery: 06/29/2015
Date of Inspection: 06/03/2025
Weather: Partly cloudy, 58°F

Spill is located within:
-Greater Sage Grouse Lek Site High Priority Habitat
-Greater Sage Grouse Priority Habitat Management Area High Priority Habitat
-Pronghorn Winter Concentration High Priority Habitat
-Range land (immediately adjacent, all directions)

Current site status:
-No remedial activities present at the spill location.

See attached corrective actions.

Inspected Facilities

Facility ID: 442351 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Per the Form 19 – Supplemental Report Document # 401832984, Spill ID 442351 was closed with work proceeding under an approved Form 27, Remediation Project # 11848.

The language within Initial Form 27 Document # 401777025 (Remediation Project # 11848) appears to align with the description of Spill ID 442351. However, Remediation Project # 11848 was created referencing Spill ID 441351, rather than Spill ID 442351. Spill ID 441351 is located approximately 123 miles away from the subject location and has received a No Further Action determination.

Corrective Action: Operator shall submit a Supplemental Form 27 to address the remediation of Spill ID 442351, removing Spill ID 441351 as a Related Facility and adding Spill ID 442351 in its place. The Supplemental Form 27 shall contain language to clarify this discrepancy.

Quarterly reporting is required under Remediation Project # 11848; the last Form 27 for this project was submitted 09/27/2018 (Document # 401777025). In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days).

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100327	ECMC Photo Log - McCallum 33 Flowline - 06.03.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7188865