

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
Location ID: 318605



Sign



Well

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
Location ID: 318605



Location

Mechanical Conditions

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
Location ID: 318605



Stained Soil

Stained Soil

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
Location ID: 318605



Unmarked Riser

Unmarked Riser

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
Location ID: 318605



Stained Soil



Stained Soil under clean soil

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
Location ID: 318605



Stained Soil

Stained Soil