

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2025

Submitted Date:

08/13/2025

Document Number:

710500573

**FIELD INSPECTION FORM**

Loc ID 381280 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 61250  
Name of Operator: MULL DRILLING COMPANY INC  
Address: 1700 N WATERFRONT PKWY B#1200  
City: WICHITA State: KS Zip: 67206-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Mull, Jennifer	(316) 264-6366	jmull@mulldrilling.com	<a href="#">All Inspections</a>
OBryhim, Risa		Risa@mullcompanies.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256400	WELL	PA	12/23/1999	DA	017-07614	DURR 1-32	EI
490670	SPILL OR RELEASE	AC	06/16/2025		-	DURR #1-32	EI

**General Comment:**

This is an Environmental Inspection for the Durr 1-32 well location located in Cheyenne County, Colorado. Spill ID 490670.

Reclamation, Field inspection Report document no. 713602256, Date 06/04/2025 Identified potential historical impacts to soils from a historical release.

Initial Form 19-i document no. 404231185 received on 06/16/2025.

Soil samples collected on 8/12/2025.

**Inspected Facilities**

Facility ID: 256400 Type: WELL API Number: 017-07614 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 490670 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: This is an Environmental Inspection for Spill ID 490670. At the time of inspection the Operator collected soil samples from areas exhibiting the highest degree of impacts, (areas with distressed vegetation). ECMC Staff was not onsite during sample collection but did arrive shortly after samples were collected. Staff was able to identify the areas where soil samples were collected within the area identified in FIR document no. 713602256.

If impacts to soils are identified the Operator shall define the vertical and lateral extent of impacts to soil through additional field sampling.

The Operator shall provide analytical data in a Supplemental Form 19.

90-day closure for Spill ID 490670 in accordance with Rule 912.b.(6) is due by September 2, 2025

Corrective Action: 90-day closure for Spill ID 490670 in accordance with Rule 912.b.(6) is due by September 2, 2025 Date: 09/02/2025

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500574	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7189127">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7189127</a>