

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2025

Submitted Date:

08/08/2025

Document Number:

715801321

**FIELD INSPECTION FORM**

Loc ID 318384 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241198	WELL	PR	08/01/2023	OW	123-08986	MARIE GERHARDT B 8	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	WEEDS		
Comment:	Vegetation needs to be cut throughout location		
Corrective Action:	Comply with rule 606	Date:	08/15/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	wood & metal post with barb wire on 3 sides		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Fabricated steel pipe around the ancillary equipment		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	wood post & barb wire		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	electric panel is off, meter box & transformers		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241198 Type: WELL API Number: 123-08986 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR electric panel is off.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary On Friday 8-8-2025 at approximately 1150 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: KP Kauffman                      Location ID: 318384                      Location name: Marie Gerhardt B 8                      API #05-123-08986                      County: Weld                      Weather: Cloudy.                      Location: Dry.                      Temp: 82*                      While there, I observed a wellsite, PR at the time of the inspection.                      During this inspection, I observed the following possible compliance:                      606 Weeds: CA date 8-15-2025.                      See attached photos.                      A follow up site inspection will be conducted to ensure that the Compliance issues are addressed and comply with ECMC rules.</p>	revasr	08/08/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404310795	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7180387">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7180387</a>
715801322	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7180383">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7180383</a>