

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/08/2025

Document Number:

718100716

**FIELD INSPECTION FORM**

Loc ID 336001 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gaasche, Emily		emily.gaasche@state.co.us	
,		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296755	WELL	AL	01/11/2018	LO	045-16126	CHEVRON 12-4D	RI
296756	WELL	AL	01/11/2018	LO	045-16127	CHEVRON 12-7D	RI
296757	WELL	AL	01/11/2018	LO	045-16128	CHEVRON 12-6D	RI
296758	WELL	AL	01/11/2018	LO	045-16129	CHEVRON 12-14D	RI
296759	WELL	AL	01/11/2018	LO	045-16130	CHEVRON 12-13D	RI
296760	WELL	AL	01/11/2018	LO	045-16131	CHEVRON 12-12D	RI
296761	WELL	AL	01/11/2018	LO	045-16132	CHEVRON 12-5D	RI
296762	WELL	AL	01/11/2018	LO	045-16133	CHEVRON 12-8D	RI
302102	WELL	AL	01/11/2018	LO	045-18362	CHEVRON 12-1D	RI
302103	WELL	AL	01/11/2018	LO	045-18363	CHEVRON 12-2D	RI
302104	WELL	AL	01/11/2018	LO	045-18364	CHEVRON 12-3D	RI
336001	LOCATION	AL			-	CHEVRON C12 697	RI

**General Comment:**

On 08/5/2025, Western Reclamation Work Lead Trujillo and Northwest Reclamation Specialist Gaasche conducted a final reclamation inspection at QB Energy Operating LLC's CHEVRON C12 697 location in Garfield County, Colorado.

Location is within the following High Priority Habitats: Elk Production Area; Greater Sage Grouse Priority Habitat Management Area

Location is in close proximity to to the following High Priority Habitats: Elk Production Area

The following compliance issues were observed during this inspection:

- Fence in disrepair
- Weed Management

Refer to the "Reclamation" section of this report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Inspected Facilities**

Facility ID: 296755 Type: WELL API Number: 045-16126 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 296756 Type: WELL API Number: 045-16127 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 296757 Type: WELL API Number: 045-16128 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 296758 Type: WELL API Number: 045-16129 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 296759 Type: WELL API Number: 045-16130 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 296760 Type: WELL API Number: 045-16131 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 296761 Type: WELL API Number: 045-16132 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 296762 Type: WELL API Number: 045-16133 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 302102 Type: WELL API Number: 045-18362 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 302103 Type: WELL API Number: 045-18363 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 302104 Type: WELL API Number: 045-18364 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 336001 Type: LOCATION API Number: - Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_ Dust and erosion control Pass

Non cropland: Revegetated 80% Pass Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

	<p>It was observed in this inspection that Noxious Weeds (Musk thistle) have established throughout the Location, and have reached seed-head maturity. Additional and ongoing weed management required.</p> <p>It was also observed that the fence along the perimeter of the Location is in disrepair. If Operator determines that fence is no longer necessary, then fence should be removed.</p>	
Corrective Action:	<p>Comply with Rules 1004.e and 606.c.: Oil and Gas Locations will be kept free of all Undesirable Plant Species.</p> <p>Maintain or remove perimeter fence.</p>	Date <b>08/15/2025</b>
<p>Overall Final Reclamation    In Process    Well Release on Active Location <input type="checkbox"/>    Multi-Well Location <input type="checkbox"/></p>		

<b>ECMC Comments</b>		
Comment	User	Date
Fence will require removal in order for the Location to receive a passing final inspection.	trujilloam	08/08/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404310223	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7179863">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7179863</a>
718100717	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7179855">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7179855</a>