

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2025

Submitted Date:

08/15/2025

Document Number:

715202769

**FIELD INSPECTION FORM**

Loc ID 321614 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

- 15 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Randel, Jason	719-767-8851	jrandel@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207522	WELL	TA	09/01/2020	OW	017-06457	RHOADES 13-35 1	PA

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a Follow up Inspection from the P&A process  
Well was plugged on 7/15/25. Operator has 30 days to remove equipment from location and begin final reclamation process

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through pasture is used for Rhoades 22-35		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by post		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Misc pipe laying by the post		
Corrective Action:	Remove pipe and wellhead from location	Date:	09/13/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Vertical Heater Treater	# 0		
Comment:	Moved to Rhoades 22-35 inventory		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Removed from location		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	One deadman is marked and needs removed		
Corrective Action:	Remove from location to begin final reclamation process	Date:	09/13/2025
Type: Pig Station	# 0		
Comment:	Removed from tank battery location		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Moved to Rhoades 22-35 inventory		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Removed from location and moved to Rhoades 22-35 inventory		
Corrective Action:	Remove electric box and post to begin final reclamation process		Date: 09/13/2025
Type: Prime Mover	# 0		
Comment:	Removed from location		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0		STEEL AST		38.870430,-102.865920
Comment:	Tanks were moved to Rhoades 22-35 inventory				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0		FIBERGLASS AST		38.870330,-102.865470
Comment:	Tanks were moved to Rhoades 22-35 inventory				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 207522 Type: WELL API Number: 017-06457 Status: TA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well was plugged on

Corrective Action: Cut, cap and cover wellhead. Continue with final reclamation process in accordance with the Final Reclamation 1004 series

Date: 09/13/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202790	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7190569">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7190569</a>