

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2025

Submitted Date:

08/15/2025

Document Number:

715202774

FIELD INSPECTION FORM

Loc ID 321818 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: 1700 N WATERFRONT PKWY B#1200
City: WICHITA State: KS Zip: 67206-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|---------------------------|---------------------------------|
| OBryhim, Risa | | ROBryhim@mulldrilling.com | All Inspections |
| Quint, Craig | | craig.quint@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 208106 | WELL | PA | 02/19/2020 | GW | 017-07041 | KERN FARMS 'A' 2 | PA |

General Comment:

SE Compliance Specialist Brian Welsh conducted a Final Routine field inspection of the location

Well was plugged on 2/19/20
Form 6S (402319521) dated 2/24/20

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----------------------|-------|----------------------|
| Yes/No | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | | Date: | <input type="text"/> |

Flaring:

| | | |
|--------------------|----------------------|----------------------------|
| Type | | |
| Comment: | <input type="text"/> | |
| Corrective Action: | | Date: <input type="text"/> |

Inspected Facilities

Facility ID: 208106 Type: WELL API Number: 017-07041 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| Well was plugged on 2/19/20. Wellhead has been cut, capped and covered. Equipment has been removed from location and ready for final reclamation. Location has been farmed over with dryland corn. Form 6S (402319521) has been Approved. Final reclamation will be verified by reclamation specialist | welshb | 08/15/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------------|---|
| 715202784 | Location is located in planted corn | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7190579 |