

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2025

Submitted Date:

08/15/2025

Document Number:

715202775

**FIELD INSPECTION FORM**

Loc ID 321696 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Quint, Craig		craig.quint@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207805	WELL	TA	05/25/2023	OW	017-06740	ARAPAHOE UNIT 131(43-25)	PA

**General Comment:**

[SE Compliance Specialist Brian Welsh conducted a Final Routine field inspection of the location](#)  
[Well was plugged on 6/4/25](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	_____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead location		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 0		
Comment:	Removed from location		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:	Removed from location		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 207805 Type: WELL API Number: 017-06740 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Well was plugged on 6/4/25. Wellhead has been cut, capped and awaiting soil sample analysis before being covered. Equipment has been removed from location and ready for final reclamation. Pile of dirt on location is for remediation process. Final reclamation will be verified by reclamation specialist	welshb	08/15/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202783	wellhead photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7190580">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7190580</a>