

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2025

Submitted Date:

08/15/2025

Document Number:

715202777

FIELD INSPECTION FORM

Loc ID 321663 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Quint, Craig		craig.quint@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207719	WELL	PA	05/31/2018	OW	017-06654	ARAPAHOE UNIT 141 (23-27)	PA

General Comment:

SE Compliance Specialist Brian Welsh conducted a Final Routine field inspection of the location

Well was plugged on 5/31/18
Form 6S (401684699) was received on 10/23/18
Form 19S (404060770) was received on 1/24/25

Location

Lease Road:			
Type	Access		
comment:	Gravel road through farm ground. Access is used for existing oil wells		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Ancillary equipment	# 0			
Comment:	Solar powered cathodic rectifier has been removed from location			
Corrective Action:		Date:		

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 207719 Type: WELL API Number: 017-06654 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well was plugged on 5/31/18. Wellhead has been cut, capped and covered. Equipment has been removed from location and ready for final reclamation. Form 6S (401684699) has been Approved. Form 19S (404060770) has been Approved. Final reclamation will be verified by reclamation specialist	welshb	08/15/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202780	South side of location looking north on the east side of the access	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7190582
715202781	South side of location looking north on the west side of the access	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7190583