

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2025

Submitted Date:

08/16/2025

Document Number:

717701648

FIELD INSPECTION FORM

Loc ID 331298 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Icke, Dean	303-249-2436	Hdpumpingservicesllc@gmail.com	
Forma, Joe	603-944-8253	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260339	WELL	TA	07/30/2020	GW	123-20458	LOST CREEK O'BRIEN 4-20	TA

General Comment:

[This is an audit of the scout card and related documents followed by a field audit.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment on the east end of the location needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	09/16/2025
Type	WEEDS		
Comment:	Overgrown vegetation around the well, separator and production tanks needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	08/25/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	Unmarked Riser next to the well need to be marked and "LO/TO". See attached photo		
Corrective Action:	Comply with the 1100 rules.		Date: 09/16/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.209500,-104.345600
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 260339 Type: WELL API Number: 123-20458 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A Form 06A on file

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/21/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary</p> <p>On Tuesday, August 12, 2025, at approximately 10:06 AM, Inspector Adam Burns conducted an on-site audit to the following location:</p> <p>Location: Lost Creek O'Brien-63N62W 20NWSE Operator: O'Brien Energy Resources Corp Location ID #331298 County: Weld</p> <p>During the audit, the following possible compliance issues were identified: Weeds: Overgrown vegetation around the well, separator and production tanks needs to be removed for good housekeeping. Comply with Rule 606. CA date of 8/25/25 Unused Equipment: Unused Equipment on the east end of the location needs to be removed for good housekeeping. Comply with Rule 606. CA date of 9/16/25 Unmarked Riser: Unmarked Riser next to the well need to be marked and "LO/TO". Comply with the 1100 rules. CA date of 9/16/25</p> <p>A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	08/16/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717701649	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7191006