

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



Photo # 1768 Entrance to location



Photo # 1783 Location – inaccurate LAT/LONG

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



Photo # 1769 Location



Photo # 1777 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



Photo # 1811 SE corner of location



Photo # 1812 SW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



Photo # 1813 NW corner of location



Photo # 1814 NE corner of location

# Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



Aug 12, 2025 at 12:24:32 PM  
+39.830275, -108.751705 ±3.45m  
Rangely



Aug 12, 2025 at 12:29:55 PM  
+39.830365, -108.751642 ±3.48m  
Rangely

Photo # 1794 Chemical tank lacks required labeling & contains inaccurate operator information

Photo # 1799 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



**Photo # 1800 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**



**Photo # 1803 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



**Photo # 1806 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**



**Photo # 1808 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #32-1 PAD

Location ID: 315161

Date: 08/12/2025



**Photo # 1809 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**

