

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 939 From entrance to location




Photo # 940 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 941 Location




Photo # 942 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 943 Location



Photo # 944 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Aug 14, 2025 at 3:28:07 PM
+39.484517,-107.716992



Aug 14, 2025 at 3:29:28 PM
+39.484547,-107.716699

Photo # 945 Location

Photo # 946 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 947 Location



Photo # 948 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 949 Location



Photo # 950 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 951 Location



Photo # 952 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 953 Unused flowlines lack lockout tagout (OOSLAT)