

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2025

Submitted Date:

08/11/2025

Document Number:

716300988

FIELD INSPECTION FORM

Loc ID 324565 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10816
Name of Operator: SILVER MOUNTAIN ENERGY LLC
Address: 31487 STATE HIGHWAY 37
City: HINTON State: OK Zip: 73047

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|----------------|----------------------------------|---------------------------|
| Flick, Jay | (580) 799-1075 | jay@sme.llc | All Forms |
| Wright, Lonnie | (405) 542-7836 | lonnie@sme.llc | All Forms |
| Wright, Taylir | (405) 952-4604 | taylir@sme.llc | All Forms |
| , | | dnr_ecmc_engineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 265121 | WELL | PR | 09/01/2024 | CO2 | 055-06285 | CADDELL 1 | PR |
| 435037 | WELL | PR | 09/01/2024 | CO2 | 055-06312 | Caddell 2 | PR |
| 439694 | WELL | SI | 12/01/2024 | LO | 055-06319 | Caddell 3 | SI |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | WELLHEAD | | |
| Comment: | PHOTO 1: CURRENT OPERATOR IS NOT LISTED ON WELL SIGN/ API # IS NOT ACCURATE ECMC RECORDS SHOW CADDELL #1 API # IS 05-055-06285 AND 911 IS NOT INCLUDED AS AN EMERGENCY CONTACT ON WELL SIGN. PHOTO 2: CURRENT OPERATOR IS NOT LISTED ON WELL SIGN/ 911 IS NOT INCLUDED AS AN EMERGENCY CONTACT ON WELLSIGN. PHOTO 3: CURRENT OPERATOR IS NOT LISTED ON WELL SIGN/ API # IS NOT ACCURATE. ECMC RECORDS SHOW CADDELL #3 API # IS 05-055-06319 AND 911 IS NOT INCLUDED AS AN EMERGENCY CONTACT ON WELL SIGN. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 08/22/2025 |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|---------------------------------------|-------|------------|
| Type | WEEDS | | |
| Comment: | PHOTO 8: TALL SHRUBS AROUND LOCATION. | | |
| Corrective Action: | MAINTAIN WEEDS PER RULE 606. | Date: | 08/22/2025 |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|--|------|--------|--|--|--|
| In Containment: | No | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |

Equipment:


| | | | |
|--------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Deadman # & Marked | # 9 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gathering Line | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |



Inspected Facilities

Facility ID: 265121 Type: WELL API Number: 055-06285 Status: PR Insp. Status: PR

Producing Well

Comment: CADDELL #1 WAS SHUT IN IN FEBUARY 2019 AND THEN PUT ON PRODUCTION IN MAY 2023 WITH NO MIT ON FILE.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 305 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435037 Type: WELL API Number: 055-06312 Status: PR Insp. Status: PR

Producing Well

Comment: CADDELL #2 WAS SHUT IN IN APRIL 2019 AND THEN PUT ON PRODUCTION IN MAY 2023 WITH NO MIT ON FILE. CAPTUREPOINT LLC. FILED A FORM 4 Alternative to MIT Request (DOC. #402919609) THAT WAS APPROVED ON 2/1/2022. THE APPROVAL WAS contingent on the well being returned to production BY 1-30-2023, THE WELL WAS NOT RETURED TO PRODUCTION UNTIL 5-1-2023.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439694 Type: WELL API Number: 055-06319 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: CADDELL #3 WAS SHUT IN IN APRIL 2019 AND THEN PUT ON PRODUCTION IN MAY 2023 WITH NO MIT ON FILE. CAPTUREPOINT LLC. FILED A FORM 4 Alternative to MIT Request (DOC. #402919620) THAT WAS APPROVED ON 2/1/2022. THE APPROVAL WAS contingent on the well being returned to production BY 1-30-2023, THE WELL WAS NOT RETURED TO PRODUCTION UNTIL 5-1-2023.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| THIS IS A FOLLOW UP TO INSP. DOC #713601422, CA HAS BEEN ADDRESSED. HOWEVER THERE ARE NEW CORRECTIVE ACTIONS LISTED IN THIS DOCUMENT. | beardslt | 05/19/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404312140 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7182485 |
| 716301383 | INSP. PHOTOS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7182477 |