

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/18/2025

Submitted Date:

08/18/2025

Document Number:

715801368

**FIELD INSPECTION FORM**

Loc ID 317665 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239739	WELL	SI	07/01/2024	GW	123-07527	UPRR 42 PAN AM E 2	SI

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	WEEDS		
Comment:	Tall vegetation throughout location, around equipment, contaminated soil & in the excavation needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	08/25/2025

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Deep excavation next to the well, the safety fencing has fallen or is missing, person or animal has no way to escape.		
Corrective Action:	Comply with the fencing requirements per the 1202.(4) A	Date:	03/11/2025

**Equipment:**

Type		#		corrective date
Bradenhead		# 1		
Comment:	exposed by excavation			
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Ancillary equipment		# 1		
Comment:	Electric panel, meter box.			
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239739 Type: WELL API Number: 123-07527 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI flow line disconnected, deep excavation next to well bore.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/14/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: exposed by the site excavation.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Monday 8-18-2025 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator: KP Kauffman                      Location # 317665                      API # 05-123-07527                      Well name: UPRR 42 Pan Am E2                      County: Weld                      Weather: Clear                      Temp: 87*                      Location: Dry                      While there, I observed a wellsite &amp; tank battery, PR at the time of inspection. During this inspection the following possible compliance issues were observed:                      606 housekeeping: Tall vegetation needs to be removed, CA date 8-25-2025.                      1202.(4).A fencing: Fencing needs to be repaired. CA date 3-11-2025.                      Any corrective actions from previous Inspections that have not been addressed are still applicable.                      See attached photos.                      A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	08/18/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801369	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193289">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193289</a>