

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2025

Submitted Date:

08/13/2025

Document Number:

717100336

FIELD INSPECTION FORM

Loc ID: 324655
Inspector Name: Rollins, Grace
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
,		cogcc@kpk.com	All Inspections
Watzman, Ross		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212274	WELL	SI	01/01/2022	ERIW	057-06167	MCCALLUM UNIT 90	EI

General Comment:

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Remediation Project # 27463. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site Name: McCallum Unit 90
Remediation Project #: 27463
Well API #: 05-057-06167
Date of Inspection: 06/04/2025
Weather: Partly cloudy, 62°F

Site is located within or adjacent to:

- Greater Sage Grouse General Habitat Management Area High Priority Habitat (eastern portion of flowline within)
- Pronghorn Migration Corridors (eastern portion of flowline within)
- Greater Sage Grouse Priority Habitat Management Area (well and southwestern portion of flowline within)
- Range land (immediately adjacent, all directions)

Current site status:

- Per Form 6 Document # 402830478, the McCallum Unit 90 well was plugged and abandoned on 09/29/2021 and cut and capped on 10/18/2021.
- The well appears to have been plugged and abandoned.
- Vegetation in the vicinity of the former well appears limited in comparison to the surrounding field.
- Trash is visible on location.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment: Trash is visible on location.

Corrective Action: Comply with Rule 606.

Date: 08/20/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 212274 Type: WELL API Number: 057-06167 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation Project # 27463 was created for the plugging and abandonment of the McCallum Unit 90 wellhead and decommissioning of the associated flowline. Per Form 6 Document # 402830478, the McCallum Unit 90 well was plugged and abandoned on 09/29/2021 and cut and capped on 10/18/2021. Vegetation in the vicinity of the former well appears limited in comparison to the surrounding field. Quarterly reporting is required under Remediation Project # 27463; the last Form 27 for this project was submitted 10/26/2022 (Document # 403110322).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 27463.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404315423	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186708
717100337	ECMC Photo Log - McCallum Unit 90 - 06.04.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186693