

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/20/2025

Document Number:

719700002

**FIELD INSPECTION FORM**

Loc ID 431674 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 23 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431671	WELL	PR	08/01/2024	OW	123-36723	Dillard 20R-443	PR
431676	WELL	PR	09/01/2019	OW	123-36727	Dillard 20R-303	PR
431677	WELL	PR	09/01/2019	OW	123-36728	Dillard 20M-203	SI

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Wellsite(s): Paraffin Inhibitor. Placards.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	Posted.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	1.) Stained soil at wellsite(s). Refer to Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions) for guidance. * All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. All equipment will be engineered, operated, and maintained within the manufacturer's recommended specifications.		
Corrective Action:	** Mitigate stained soil around wellsite(s). Comply with Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions). See photo(s) #6, 7.		Date: <u>09/04/2025</u>
Type	WEEDS		
Comment:	CORRECTIVE ACTION Item(s): 2.) Overgrown vegetation at wellsite(s). Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around wellsite(s). Comply with Rule 606.c. See photo(s) #3, 8.		Date: <u>09/04/2025</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Wellsite(s): 2 Iron mesh panel.		
Corrective Action:			Date:

Type	OTHER		
Comment:	Gas Lift injection meter(s), header(s): 1 Iron panel.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellsite(s): 3 Iron panel, barbed wire.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 3		
Comment:	Wellsite(s): 3 Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellsite(s): 1 Gas lift injection line(s).		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Wellsite(s): 1		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Wellsite(s): 1: Gas Lift Allocation; (Chevron). Calibration card(s) indicates calibration <= 1 year. Last calibration: 07/28/2025.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Wellsite(s): 4: Paraffin inhibitor pump(s), tank(s) w/ drip containment.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Wellsite(s): 2		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Wellsite(s): 2 Gas engine(s) drive pump jack(s).		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.565236,-104.572870
Comment:	Centralized Battery serves 1 Location ID (431674). (Well(s): 2: Producing   PR; 1: Shut-In   SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 431671 Type: WELL API Number: 123-36723 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 02/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431676 Type: WELL API Number: 123-36727 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 02/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431677 Type: WELL API Number: 123-36728 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut-In | SI.  
Observed prod. valves shut.  
ECMC records last prod: 06/2025.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>This is a WELL inspection. Well(s): 2: Producing   PR; 1: Shut-In   SI. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (431674). (Well(s): 2: Producing   PR; 1: Shut-In   SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700002 and/or Location ID #431674 for PR, SI Well(s) info. B.) Field Inspection Report doc. #719700004 and/or Location ID #431674 for Battery / Facility, Equipment info.</p>	evinsb	08/20/2025
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 08/05/2025 at approximately 15:16 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: Dillard/20M-HZ Pad Location ID: 431674 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 2: Producing   PR; 1: Shut-In   SI. Battery: Active.</p> <p>*CORRECTIVE ACTIONS Item(s): 2.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/20/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700003	Inspection photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7197691">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7197691</a>