

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 1060 From entrance to location



Photo # 1061 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 1062 Location



Photo # 1063 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 1064 Location



Photo # 1065 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 1066 Location



Photo # 1067 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



**Photo # 1068 Pneumatic control valve on Summit Midstream pipeline has been modified/valve no longer has the ability to close**




**Photo # 1069 Pneumatic control valve on Summit Midstream pipeline has been modified/valve no longer has the ability to close**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



**Photo # 1070 Pneumatic control valve on Summit Midstream pipeline has been modified/valve no longer has the ability to close**