

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2001 Entrance to location

Photo # 2010 Location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2002 Location



Photo # 2008 Location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2016 NE corner of location



Photo # 2017 NW corner of location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2018 SW corner of location



Photo # 2019 SE corner of location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2025 Unmarked deadman



Photo # 2026 Debris

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2028 Debris



Photo # 2030 Stockpiled soils with no BMP's

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2033 Stockpiled soils with no BMP's



Photo # 2037 Stockpiled soils with no BMP's

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-4 PAD

Location ID: 314344

Date: 08/18/2025



Photo # 2038 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 2040 Failure to minimize erosion & transport of sediment off location/insufficient BMP's