

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2025

Submitted Date:

08/14/2025

Document Number:

697011792

FIELD INSPECTION FORM

Loc ID 435175 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 22 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435172	WELL	SI	02/01/2025	OW	123-38493	Weld 152 41-10CHZ	SI
435173	WELL	PR	06/01/2020	OW	123-38494	Weld 152 41-10NHZ	PR
435174	WELL	PR	02/01/2025	OW	123-38495	Weld 152 31-10CHZ	PR
435189	WELL	PR	04/01/2025	OW	123-38501	Weld 152 C-10CHZ	PR
435190	WELL	PR	04/01/2025	OW	123-38502	Weld 152 C-10NHZ	PR
435191	WELL	PR	04/07/2015	OW	123-38503	Weld 152 31-10NHZ	PR

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	All chemical systems placards require replacement, see attached photo.		
Corrective Action:	Install signs to comply with Rule 605.h.	Date:	11/14/2025
Type	WELLHEAD		
Comment:	x 6		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Damaged 400 bbl fiberglass tank and pipe next to wellheads, see attached photos.		
Corrective Action:	Comply with Rule 606	Date:	11/14/2025
Type	TRASH		
Comment:	Bag of fertilizer at meter run, see attached photo.		
Corrective Action:	Comply with Rulu 606.	Date:	11/14/2025
Type	WEEDS		
Comment:	Weeds were observed around the location, see attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	11/14/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
------	----------	--	--

Comment:	Panel		
Corrective Action:			Date:
Equipment:			corrective date
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 6		
Comment:	Pilots are on		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 6		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Automation array, solar array, ECD scrubbers, nitrogen system, chemical systems in secondary containment, bulk lube oil storage in secondary containment with wildlife protection		
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	DCP calibration card is current.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

Type: Prime Mover	# 1	
Comment:	Natural gas engine on compressor	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined berm			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV CONCRETE		,
Comment:	60 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Lined berm				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 435172 Type: WELL API Number: 123-38493 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435173 Type: WELL API Number: 123-38494 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435174 Type: WELL API Number: 123-38495 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435189 Type: WELL API Number: 123-38501 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435190 Type: WELL API Number: 123-38502 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435191 Type: WELL API Number: 123-38503 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	
		Tracking Pad	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On Thursday 8/14/2025 at approximately 13:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDCE Weld 152 31-10 CHZ location #435175 in Weld County, Colorado. While there, I observed that the chemical systems required new placards, unused equipment, trash and weeds around the location. During this inspection the following possible compliance issues were observed: Rule 605.h. with a corrective action date of 11/14/2025, Rule 606. with a corrective action date of 11/14/2025. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	petersont	08/14/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404317593	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7188887
697011793	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7188864