

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2025

Submitted Date:

08/21/2025

Document Number:

715202802

FIELD INSPECTION FORM

Loc ID 321900 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Randel, Jason	719-767-8851	jrandel@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208448	WELL	PR	04/08/1996	OW	017-07383	CHRISTOPHER 43-1 4	PR

General Comment:

[This is a field audit of the scout card, related documents and the location by SE Compliance Specialist Brian Welsh](#)

Location			
Lease Road:			
Type	Access		
comment:	Elevated gravel road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on water tanks		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Stickers on chemical drums and propane tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Tan tanks stored on north and west edge of location while remediation project is ongoing. Tanks will be used when remediation is finished		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Wire fence around tank battery and compressor yard		
Corrective Action:			Date:

Type	OTHER		
Comment:	Fencing around remediation projects		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around REA pole north of wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	Treater w/metal shed on east side of water tanks		
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	Electric panel, cathodic rectifier, chemical drums w/containment, electric panel and electric circ pump at battery		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 456		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	25 HP Electric motor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	400 BBLs	FIBERGLASS AST		39.025440,-103.059480
Comment:	Far east tank with metal shed has been removed				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		39.025160,-103.059510

Comment:	West tan tank next to treater. Tank is temporary battery while remediation project is open				
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		39.025160,-103.059510
Comment:	East tan tank next to treater. Tank is temporary battery while remediation project is open				
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		39.025440,-103.059480
Comment:	1 blue oil tank on north side of location next to remediation project. Tank is still plumbed into production but is empty and has manway cover removed				
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:	Tank is partially bermed due to remedation project				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 208448 Type: WELL API Number: 017-07383 Status: PR Insp. Status: PR

Producing Well

Comment: [Well is SI at time of inspection. Central tank battery for \(Christopher 4,5,6, Bledsoe 3-12\) 1950' SW @ 39.025440/-103.059480](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202809	pumping unit	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199013
715202811	NE corner of tank battery looking SW	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199014
715202812	treater and tank battery	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199015