

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2025

Submitted Date:

08/21/2025

Document Number:

715202804

**FIELD INSPECTION FORM**

Loc ID 321893 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Randel, Jason	719-767-8851	jrandel@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208430	WELL	PR	01/31/1996	OW	017-07365	BLEDSOE 3-12	PR

**General Comment:**

This is a field audit of the scout card, related documents and the location by SE Compliance Specialist Brian Welsh

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Partially elevated gravel road through pasture with cattle guard		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to metal shed. Sticker is peeling off and needs replaced		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Ancillary equipment	# 3		corrective date
Comment:	Electric panel, cathodic rectifier, chemical drum w/containment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	25 HP Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Sunward 640		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 208430 Type: WELL API Number: 017-07365 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well is SI at time of inspection. Central tank battery for (Christopher 4,5,6, Bledsoe 3-12)  
1600' NE @ 39.025440/-103.059480

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202808	pumping unit	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199016">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199016</a>