

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-2 PAD

Location ID: 314341

Date: 08/18/2025



Photo # 2049 Entrance to location



Photo # 2050 Location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-2 PAD

Location ID: 314341

Date: 08/18/2025



Photo # 2051 Wellhead sign lacks quarter/quarter section information. Additionally operator label is peeling but still legible.

Photo # 2062 Location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-2 PAD

Location ID: 314341

Date: 08/18/2025



Photo # 2063 Tank battery sign

Photo # 2076 SW corner of location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-2 PAD

Location ID: 314341

Date: 08/18/2025



Photo # 2077 NW corner of location



Photo # 2078 NE corner of location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-2 PAD

Location ID: 314341

Date: 08/18/2025



Photo # 2079 SE corner of location




Photo # 2060 Small amount of weeds near wellhead

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-2 PAD

Location ID: 314341

Date: 08/18/2025



Photo # 2069 Small amount of weeds in secondary containment



Photo # 2073 Stockpiled soils with no BMP's

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY A-2 PAD

Location ID: 314341

Date: 08/18/2025



Photo # 2075 Stockpiled soils with no BMP's



Photo # 2080 Debris