

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2096 Entrance to location



Photo # 2097 Location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2099 Wellhead sign lacks nearest public road access information. Additionally operator name is weathered & cracking/starting to become illegible

Photo # 2146 NE corner of location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2147 SE corner of location



Photo # 2148 SW corner of location

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2149 NW corner of location



Photo # 2105 Improperly covered wellhead cellar lacks wildlife egress/available for entry by wildlife

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2112 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 2117 Failure to minimize erosion & transport of sediment onto location/insufficient BMP's

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2118 Failure to minimize erosion & transport of sediment onto location/insufficient BMP's



Photo # 2119 Failure to minimize erosion & transport of sediment onto location/insufficient BMP's

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2121 Failure to minimize erosion & transport of sediment onto location/insufficient BMP's

Photo # 2122 Failure to minimize erosion & transport of sediment onto location/insufficient BMP's

Inspection/Audit Photos

Location: PLUG NICKEL OIL COMPANY INC MURPHY-GOVERNMENT 1-B PAD

Location ID: 314340

Date: 08/18/2025



Photo # 2126 Failure to minimize erosion & transport of sediment onto location/insufficient BMP's



Photo # 2144 Staining