

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2295 Entrance to location



Photo # 2296 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Aug 20, 2025 at 11:48:42 AM
+39.878338,-108.760936 ±4.75m
Rangely



Aug 20, 2025 at 12:01:24 PM
+39.878314,-108.761077 ±3.54m
Rangely

Photo # 2301 Location

Photo # 2316 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2323 Location



Photo # 2336 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2337 NE corner of location



Photo # 2338 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2339 SW corner of location



Photo # 2298 Wellhead sign lacks required information

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2315 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 2322 Label is weathered & starting to peel

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2325 Battery sign lacks required information/not in compliance with CECMC rules

Photo # 2333 Debris

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2334 Debris



Photo # 2335 Debris

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #E-17-2-101-S PAD

Location ID: 315607

Date: 08/20/2025



Photo # 2343 Debris