

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #H-18-2-101-S PAD

Location ID: 315606

Date: 08/20/2025



Photo # 2348 Entrance to location



Photo # 2349 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #H-18-2-101-S PAD

Location ID: 315606

Date: 08/20/2025



Photo # 2356 Location



Photo # 2385 NW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #H-18-2-101-S PAD

Location ID: 315606

Date: 08/20/2025



Photo # 2386 NE corner of location



Photo # 2387 SE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #H-18-2-101-S PAD

Location ID: 315606

Date: 08/20/2025



Photo # 2388 SW corner of location



Photo # 2350 Wellhead sign lacks required information

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #H-18-2-101-S PAD

Location ID: 315606

Date: 08/20/2025



Photo # 2358 Battery sign lacks required information/not in compliance with CECMC rules, also Lat/Long is inaccurate



Photo # 2362 Separator door open to wildlife/available for entry by wildlife

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #H-18-2-101-S PAD

Location ID: 315606

Date: 08/20/2025



Photo # 2366 Chemical tank label is not legible/not in compliance with CECMC rules



Photo # 2378 Possible leak on production tank/tank appears to lack integrity

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #H-18-2-101-S PAD

Location ID: 315606

Date: 08/20/2025



**Photo # 2381 Possible leak on production tank/tank appears to lack integrity**