

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/18/2025

Submitted Date:

08/18/2025

Document Number:

715801374

**FIELD INSPECTION FORM**

Loc ID 333225 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239679	WELL	SI	05/01/2021	OW	123-07467	CAMENISCH 1	SI

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate, the sign is faded, & getting hard to read & needs to be updated.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate, the sign is faded, & getting hard to read & needs to be updated.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Tall vegetation throughout the location & around the equipment needs to be removed.		
Corrective Action:	Comply with rule 606	Date:	08/25/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	wood/metal post & barbwire needs attention		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	wood/metal post & barbwire needs attention		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated round stock		
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	automation,electric panel & meter box		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	vegetation needs to be removed			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)	210 bbl			
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:
<b>Wells Served By Facilities Above</b>				
API Number		AirsID		
123-07467				
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 239679 Type: WELL API Number: 123-07467 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, the well is part of a 901 Order.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/14/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Submit test results to the ECMC.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Monday 8-18-2025 at approximately 1520 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator: KP Kauffman                      Location # 333225                      API # 05-123-07467                      Well name: Camenisch 1                      County: Weld                      Weather: Clear                      Temp: 92*                      Location: Dry                      While there, I observed a wellsite &amp; tank battery, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      606 housekeeping: Tall vegetation needs to be removed, CA date 8-25-2025.                      Any corrective actions from previous Inspections that have not been addressed are still applicable.                      See attached photos.                      A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	08/18/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404320945	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193318">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193318</a>
715801375	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193292">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193292</a>