

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around pumpjack. See attached photos		
Corrective Action:	Comply with Rule:606	Date:	09/02/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202638 Type: WELL API Number: 001-08043 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On (8/25/2025) at approximately (11:46am). I, Inspector Keith Huck, conducted an on-site inspection. Operator: KPK Location name: ZARLENGO #4 API #05-001-08043 Location ID #:320458 County: Adams While there, I observed a (PR) well. During this inspection the following possible compliance issues were observed: Weeds unmanaged Pumpjack. See attached pictures Comply with Rule: 606 Corrective Action Date: 9/2/25 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	huckk	08/25/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716900146	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7203604