

Final Reclamation Inspection

August 5, 2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 330667

Inspection Document #: 718800690

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: D.O.C. SHOWERS #32-12-10
Location ID: 330667



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but the location does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*) were observed across the location.



Photo 2. Photo taken of the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: D.O.C. SHOWERS #32-12-10
Location ID: 330667



Photo 3. Photo taken of the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: D.O.C. SHOWERS #32-12-10

Location ID: 330667



Photo 5. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the access road to the well location, facing west. Photo illustrates that the access road fails to meet Rule 1004 standards as gravel remains and weedy annual vegetation was observed across the location.



Inspection Photos
Location Name: D.O.C. SHOWERS #32-12-10
Location ID: 330667



Photo 7. Photo taken of the access road to the well location, facing east. See comments under Photo 6.



Photo 8. Photo taken of ground cover along the access road. Photo illustrates gravel and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.

Inspection Photos
Location Name: D.O.C. SHOWERS #32-12-10
Location ID: 330667



Photo 9. Photo taken of the tank battery location, facing north. Photo illustrates the operator sign and fencing at the entrance to the location.



Photo 10. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Gravel and weedy annual vegetation were observed across the location.



Inspection Photos

Location Name: D.O.C. SHOWERS #32-12-10

Location ID: 330667



Photo 11. Photo taken of the tank battery location facing northwest. See comments under Photo 10.



Photo 12. Photo taken of the tank battery location, facing northeast. See comments under Photo 10.



Inspection Photos
Location Name: D.O.C. SHOWERS #32-12-10
Location ID: 330667



Photo 13. Photo taken of the tank battery location, facing south. See comments under Photo 10.



Photo 14. Photo taken of ground cover at the tank battery location. Photo illustrates gravel and weedy annual vegetation including kochia (*Bassia scoparia*).



Inspection Photos
Location Name: D.O.C. SHOWERS #32-12-10
Location ID: 330667



Photo 15. Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass vegetation.

