

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2025

Submitted Date:

08/19/2025

Document Number:

715801390

**FIELD INSPECTION FORM**

Loc ID 317757 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239927	WELL	SI	05/01/2021	OW	123-07715	DOVERSBERGER, EUGENE 2	SI

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate, it needs to be picked up off the ground & reattached to the PJ fence.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	WEEDS		
Comment:	tall vegetation throughout location & around equipment needs to be removed		
Corrective Action:	Compy with rule 606	Date:	08/26/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	fabricated steel pipe around the ancillary equipment		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron.		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box & transformers		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239927 Type: WELL API Number: 123-07715 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, the well is part of a 901 Order.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/05/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: plumbed to surface

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Tuesday 8-19-2025 at approximately 1425 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator: KP Kauffman                      Location # 317757                      API #05-123-07715                      Well name: Doversberger, Eugene 2                      County: Weld                      Weather: Cloudy &amp; clear                      Temp: 91*                      Location: Dry                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      606 Housekeeping: vegetation needs to be removed, CA 8-26-2025.                      Any corrective actions from previous Inspections that have not been addressed are still applicable                      See attached photos.                      A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	08/19/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404322748	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7195251">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7195251</a>
715801391	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7195229">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7195229</a>